

Illinois Commerce Commission**Pipeline Safety****Pipeline Safety Report****Inspection #: 2014-P-00437**

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Exit Meeting Contact: Joe Orsa	Total Man Days: 1
Pipeline Safety Representative(s): Charles Gribbins	
Company Representative to Receive Report: Michael Fuller	<u>Emailed Date:</u>
Company Representative's Email Address: mfuller2@ameren.com	11/18/2014

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Centralia	Charles Gribbins	Centralia Storage	1	11/13/2014	Joe Orsa, Mike Kershaw

Statement of Activities

On November 13, 2014, Staff conducted a Storage Field Audit to determine compliance with applicable IL Adm. Codes and Code of Federal Regulations adopted via IL Adm. Part 590. The audit included field verification of the transmission system in the Centralia Storage Field. See the attached checklist for information related to the Storage Field Audit.

Staff conducted a visual inspection of the following well sites:

Perrine A Well #2

Perrine Well #3

Perrine Well #4

Castellari-Koelling Well #1

Apple Well #1

Perrine-Copple Well #2

DB Perrine Well #6

DB Perrine Well #5

Exit Statement**INSPECTION FINDINGS****Standard Inspection - Field Audit****Issues(s) Found:**

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

Illinois Commerce Commission
Pipeline Safety
Pipeline Safety Report

Inspection #: 2014-P-00437

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]